


Detail of exposed [redacted]




Legend

- Control Points
- Transmitter Connection

[redacted]

Flow Direction
- 0.5 Ft/s

Detail of exposed [redacted] with broken segment - [redacted]




500 ft



DEPTH OF COVER STUDY
DATE(S): 08/10/20 & 08/11/20

Multi-Beam Sonar Imagery Pg 1

PREPARED FOR:



Flow Direction
~ 0.5 ft/s

Flow Direction
~ 0.5 ft/s

Perspective view of exposed

Upstream sediment elevation = 429.9'

Scour hole elevation = 428.3'

TOP elevation = 430.3'

1.5'

20'



30 ft



Google Earth




DEPTH OF COVER STUDY
DATE(S): 08/10/20 & 08/11/20

Multi-Beam Sonar Imagery Pg 2

PREPARED FOR:



	DEPTH OF COVER STUDY DATE(S): 08/10/20 & 08/11/20
	Multi-Beam Sonar Imagery Pg 3
PREPARED FOR:	